



**To:**  
ATR

FLT OPS / TECH / 57 / Mon Nov 21 2016  
Mon Nov 21 2016

**Subject: ATR - NO OIL PRESSURE RISE DURING ENGINE START**

This is with reference to no oil pressure rise during engine start.

Query was sent to ATR for their comments. We have recieved the following reply:

"During engine start, if engine oil pressure dose not increase after 10s, the engine should be shut down".

This corresponds to the "NO NH DURING START" procedure (FCOM 2.05.02 and QRH 2.05).

This is for your information and compliance.

Mon Nov 21 2016  
Capt. MASOOD ALEEM OPEL  
Chief Pilot Technical  
Flight Operation Department

**CC:** -----